HAZARDOUS SUBSTANCE STORAGE CONTAINER INFORMATION FOR CONTRA COSTA COUNTY
CONTAINER TYPES: 1,2,3,4,5
(1=FARM MOTOR VEHICLE FUEL TANKS, 2=ALL OTHER PRODUCT TANKS, 3=WASTE TANKS, 4=SUMPS, 5=PITS, PONDS, LAGOONS & OTHERS)

I OWNER
ATLAS WELDING SUPPLY INC.
124 6TH STREET BERKELEY CA 94710

II FACILITY

	MAILING ADDRESS TOWNSHIP/RANGE/SECTION	DEALER/FOREMAN/SUPERVISOR TELEPHONE	TYPE OF BUSINESS NO. OF CONTAINERS
ATLAS WELDING SUPPLY 1224 6TH ST. CA 94710	1224 6TH ST. CA 94710	WAYNE RASMUSSEN (415) 524-5117	RETAILOR 1

CROSS STREET :
GILMAN

III 24-HR. CONTACT PERSON / TELEPHONE
DAY: RASMUSSEN WAYNE (415) 524-5117 NIGHT: RASMUSSEN WAYNE (415) 841-3650

********** OWNER ASSIGNED CONTAINER NUMBER: #1 ********** STATE BOARD ASSIGNED CONTAINER ID NUMBER: 00000032835001 *********

IV DESCRIPTION
A. CONTAINER TYPE : TANK
B. MANUFACTURER/YR OF MFG: /
C. YEAR INSTALLED : UNK
D. CAPACITY (GALLONS) : 1,000
E. REPAIRS : NONE IF YES WHEN :
F. CURRENTLY USED : YES IF NO, YEAR OF LAST USE:
G. STORES : PRODUCT
H. MOTOR VEHICLE FUEL/WASTE OIL : YES CONTAINS: REGULAR

IS CONTAINER LOCATED ON A FARM : NO

V CONTAINER CONSTRUCTION
A. THICKNESS: B. VAULTING: UNKNOWN C. WALLING: UNKNOWN
D. MATERIAL : UNKNOWN
E. LINING : UNKNOWN
F. WRAPPING : UNKNOWN

VI PIPING
A. ABOVEGROUND PIPING : B. UNDERGROUND PIPING : SUCTION
C. REPAIRS : NONE IF YES, YEAR OF MOST RECENT REPAIR:

VII LEAK DETECTION
PRESSURE TEST

VIII CHEMICAL COMPOSITION OF SUBSTANCES CURRENTLY STORED IN CONTAINER
12032 REGULAR MOTOR VEHICLE FUEL