*** CO2 ***

STATE WATER RESOURCES CONTROL BOARD
HAZARDOUS SUBSTANCE STORAGE CONTAINER INFORMATION FOR LOS ANGELES COUNTY
CONTAINER TYPES: 1,2,3,4,5
(1=FARM MOTOR VEHICLE FUEL TANKS, 2=ALL OTHER PRODUCT TANKS, 3=WASTE TANKS, 4=SUMPS, 5=PITS, PONDS, LAGOONS & OTHERS)

I OWNER
BEVERLY ENTERPRISES
873 S FAIR OAKS AVE. PASADENA CA 91105

II FACILITY

	MAILING ADDRESS / TOWNSHIP/RANGE/SECTION	DEALER/FOREMAN/SUPERVISOR / TELEPHONE	TYPE OF BUSINESS / NO. OF CONTAINERS
RUSH PHARMACY 67 WEST BELLEVUE DRIVE PASADENA CA 91105	67 WEST BELLEVUE DRIVE PASADENA CA 91105	JOHN COGSWELL (213) 795-3206	PHARMACY 1

CROSS STREET :
FAIR OAKS

III 24-HR. CONTACT PERSON / TELEPHONE
DAY: COGSWELL,J. (213) 795-3206 NIGHT: ( ) -

********** OWNER ASSIGNED CONTAINER NUMBER: 1 ********** STATE BOARD ASSIGNED CONTAINER ID NUMBER: 0000000358600 1 *********

IV DESCRIPTION
A. CONTAINER TYPE : TANK
B. MANUFACTURER/YR OF MFG: KEESEE TANK CO. /1979
C. YEAR INSTALLED : 1979
D. CAPACITY (GALLONS) : 9,940
E. REPAIRS : NONE IF YES WHEN :
F. CURRENTLY USED : YES IF NO, YEAR OF LAST USE:
G. STORES : PRODUCT
H. MOTOR VEHICLE FUEL/WASTE OIL : YES CONTAINS: UNLEADED

IS CONTAINER LOCATED ON A FARM : NO

V CONTAINER CONSTRUCTION
A. THICKNESS:
B. VAULTING: NON-VAULTED
C. WALLING: SINGLE
D. MATERIAL : CARBON STEEL
E. LINING : UNLINED
F. WRAPPING : UNKNOWN

VI PIPING
A. ABOVEGROUND PIPING :
B. UNDERGROUND PIPING : SUCTION
C. REPAIRS : NONE IF YES, YEAR OF MOST RECENT REPAIR:

VII LEAK DETECTION
NONE

VIII CHEMICAL COMPOSITION OF SUBSTANCES CURRENTLY STORED IN CONTAINER
12031 UNLEADED MOTOR VEHICLE FUEL