STATE WATER RESOURCES CONTROL BOARD
HAZARDOUS SUBSTANCE STORAGE CONTAINER INFORMATION FOR LOS ANGELES COUNTY
CONTAINER TYPES: 1,2,3,4,5
(1=FARM MOTOR VEHICLE FUEL TANKS, 2=ALL OTHER PRODUCT TANKS, 3=WASTE TANKS, 4=SUMPS, 5=PITS, PONDS, LAGOONS & OTHERS)

I OWNER
HITCO-MATERIALS DIVISION
1600 WEST 135TH STREET GARDENA CA 90249

II FACILITY

	MAILING ADDRESS / TOWNSHIP/RANGE/SECTION	DEALER/FOREMAN/SUPERVISOR / TELEPHONE	TYPE OF BUSINESS / NO. OF CONTAINERS
HITCO-MATERIALS DIVISION 1600 WEST 135TH STREET GARDENA CA 90249	1600 WEST 135TH STREET GARDENA CA 90249	JACK CONNER (213) 321-8080	MANUFACTURING 1

CROSS STREET :
WESTERN AVENUE

III 24-HR. CONTACT PERSON / TELEPHONE
DAY: BURLINGAME, D. ARVIN (213) 321-8080 NIGHT: BURLINGAME, D. ARVIN (818) 286-3447

********** OWNER ASSIGNED CONTAINER NUMBER: B-1049 ********** STATE BOARD ASSIGNED CONTAINER ID NUMBER: 0000001898900I *********

IV DESCRIPTION
A. CONTAINER TYPE : TANK
B. MANUFACTURER/YR OF MFG: BUEHLER /1977
C. YEAR INSTALLED : 1977
D. CAPACITY (GALLONS) : 30,000
E. REPAIRS : NONE IF YES WHEN :
F. CURRENTLY USED : YES IF NO, YEAR OF LAST USE:
G. STORES : PRODUCT
H. MOTOR VEHICLE FUEL/WASTE OIL : YES CONTAINS: DIESEL

IS CONTAINER LOCATED ON A FARM : NO

V CONTAINER CONSTRUCTION
A. THICKNESS: 3/8 INCHES B. VAULTING: NON-VAULTED C. WALLING: SINGLE
D. MATERIAL : CARBON STEEL
E. LINING : UNLINED
F. WRAPPING : ASPHALT TAR OR ASPHT

VI PIPING
A. ABOVEGROUND PIPING : UNKNOWN B. UNDERGROUND PIPING : SUCTION
C. REPAIRS : NONE IF YES, YEAR OF MOST RECENT REPAIR:

VII LEAK DETECTION
STOCK INVENTORY

VIII CHEMICAL COMPOSITION OF SUBSTANCES CURRENTLY STORED IN CONTAINER
12034 DIESEL MOTOR VEHICLE FUEL