STATE WATER RESOURCES CONTROL BOARD
HAZARDOUS SUBSTANCE STORAGE CONTAINER INFORMATION FOR LOS ANGELES COUNTY
CONTAINER TYPES: 1,2,3,4,5
(1=FARM MOTOR VEHICLE FUEL TANKS, 2=ALL OTHER PRODUCT TANKS, 3=WASTE TANKS, 4=SUMPS, 5=PITS, PONDS, LAGOONS & OTHERS)

I OWNER
STANDARD BRANDS PAINT COMPANY
4300 W. 190TH STREET TORRANCE CA 90509

II FACILITY

	MAILING ADDRESS	DEALER/FOREMAN/SUPERVISOR	TYPE OF BUSINESS
STANDARD BRANDS PAINT - #2	TOWNSHIP/RANGE/SECTION	TELEPHONE	NO. OF CONTAINERS
401 (FAIR OAKS PASADENA CA 91103	401 (FAIR OAKS PASADENA CA 91103	MARK COLEMAN	RETAIL PAINT
CROSS STREET :		(818) 793-2994	1

III 24-HR. CONTACT PERSON / TELEPHONE
DAY: WILLIAMS, STEVE (213) 542-5901 NIGHT: WILLIAS, S. (213) 425-8733

********** OWNER ASSIGNED CONTAINER NUMBER: SBP-002-1 ********** STATE BOARD ASSIGNED CONTAINER ID NUMBER: 00000017000001 *********

IV DESCRIPTION
A. CONTAINER TYPE : TANK
B. MANUFACTURER/YR OF MFG: N/A /1974
C. YEAR INSTALLED : 1974
D. CAPACITY (GALLONS) : 10,000
E. REPAIRS : NONE IF YES WHEN :
F. CURRENTLY USED : YES IF NO, YEAR OF LAST USE:
G. STORES : PRODUCT
H. MOTOR VEHICLE FUEL/WASTE OIL : NO CONTAINS:

IS CONTAINER LOCATED ON A FARM : NO

V CONTAINER CONSTRUCTION
A. THICKNESS: 3/8 INCHES B. VAULTING: NON-VAULTED C. WALLING: SINGLE
D. MATERIAL : CARBON STEEL
E. LINING : UNLINED
F. WRAPPING : NONE

VI PIPING
A. ABOVEGROUND PIPING : B. UNDERGROUND PIPING : SUCTION
C. REPAIRS : NONE IF YES, YEAR OF MOST RECENT REPAIR:

VII LEAK DETECTION
STOCK INVENTORY

VIII CHEMICAL COMPOSITION OF SUBSTANCES CURRENTLY STORED IN CONTAINER
64742-47-8 NOT ON LIST