PAGE 2138 STATE WATER RESOURCES CONTROL BOARD 05/27/89

HAZARDOUS SUBSTANCE STORAGE CONTAINER INFORMATION FOR ALAMEDA COUNTY

CONTAINER TYPES: 1,2,3,4,5

(1=FARM MOTOR VEHICLE FUEL TANKS, 2=ALL OTHER PRODUCT TANKS, 3=WASTE TANKS, 4=SUMPS, 5=PITS, PONDS, LAGOONS & OTHERS)

I OWNER
KEBLER COMPANY
3875 BAY CENTER PLACE HAYWARD CA 94545

II FACILITY

	MAILING ADDRESS / TOWNSHIP/RANGE/SECTION	DEALER/FOREMAN/SUPERVISOR / TELEPHONE	TYPE OF BUSINESS / NO. OF CONTAINERS
KEBLER COMPANY 3875 BAY CENTER PLACE HAYWARD CA 94545	3875 BAY CENTER PLACE HAYWARD CA 94545	WILLIAM DILL (415) 786-1991	DISTRIBUTION 1

CROSS STREET :
CLAWITER

III 24-HR. CONTACT PERSON / TELEPHONE
DAY: WILLIAM DILL (415) 786-1991 NIGHT: WILLIAM DILL (415) 426-0280

********** OWNER ASSIGNED CONTAINER NUMBER: 416 ********** STATE BOARD ASSIGNED CONTAINER ID NUMBER: 0000006551000I *********

IV DESCRIPTION
A. CONTAINER TYPE : TANK
B. MANUFACTURER/YR OF MFG: MODERN WELD /1985
C. YEAR INSTALLED : 1985
D. CAPACITY (GALLONS) : 10,000
E. REPAIRS : NONE IF YES WHEN :
F. CURRENTLY USED : YES IF NO, YEAR OF LAST USE:
G. STORES : PRODUCT
H. MOTOR VEHICLE FUEL/WASTE OIL : YES CONTAINS: DIESEL

IS CONTAINER LOCATED ON A FARM : NO

V CONTAINER CONSTRUCTION
A. THICKNESS: 20 INCHES B. VAULTING: NON-VAULTED C. WALLING: DOUBLE
D. MATERIAL : GLASTEEL OTHER
E. LINING : GLASS
F. WRAPPING : UNKNOWN

VI PIPING
A. ABOVEGROUND PIPING : B. UNDERGROUND PIPING : SUCTION
C. REPAIRS : NONE IF YES, YEAR OF MOST RECENT REPAIR:

VII LEAK DETECTION
SENSOR INSTRUMENT

VIII CHEMICAL COMPOSITION OF SUBSTANCES CURRENTLY STORED IN CONTAINER
T2034 DIESEL MOTOR VEHICLE FUEL